

SITE PHOTOGRAPHS

Of

Bioengineering works

in

Sundali nala

after 6 months of construction



Plate No. 1: Close view of the Sundali nala gully and performance of the plant growth after 6 months of bioengineering construction



Plate No. 2: Close view of the brush layering technique behind the barbed fence in Sundali nala gully and performance of the growth after 6 months of bioengineering construction.



Plate No. 3: Several rows of brushlayering works in Sundali nala gully and performance of the growth after 6 months of construction.



Plate No. 4: View of the upper part of Sundali nala gully showing bamboo cribwall construction after 6 months of construction.



Plate No. 5: Vegetated palisade construction in the Sundali nala and performance of the growth after 6 months.



Plate No. 6: Live fascine construction in Sundali nala gully and performance of the growth after 6 months.